HERCULITE 80M

HEAT: 500 °C
SPEED: 40%

HEAT: 430 °C
SPEED: 4

Hot Air Welding
HEAT: 450 °C
SPEED: 6 M/MIN

Hot Wedge Welding
HEAT: 430 °C
SPEED: 5 M/MIN

Hot Air Welding
HEAT: 450 °C
SPEED: 6 M/MIN

Hot Wedge Welding
HEAT: 430 °C
SPEED: 5 M/MIN



HEAT: 730 °C
SPEED: 10 M/MIN

***All published weldi settings are estimate ranges. The settings of your machine may vary greatly.
The testing of all seams and all fabrics is the exclusive responsibility of the operator.

MILLER WELDMASTER®
The First Choice Globally

4220 Alabama Ave
Navarre | Ohio | 44662 USA
Phone. 330 - 833 - 6739 | Fax. 330 - 837 - 2828
www.weldmaster.com | **sales@weldmaster.com**